

HANDY 6 PYROMETER with charging and calibration station

An essential IS machine tool

- Improved design
- User friendly display
- $\ensuremath{\cdot}$ Easy T° readings with immediate response
- · Adjustable colour and backlighting setting
 - → green = T° OK
 - → red = T° not OK
 - → Range: from +/-5°C to 20°C
- Precision: +/- 1% of measurement
- Temperature range: 350° to 650°C / 662°F to 1202°F
- Adjustable emissivity from 0.2 to 1.0
- Available with 300 measurements memory
- Data transfer to Windows PC via USB
- Supplied with either a probe at a 90° angle or a probe at a 45° angle
- Resistant to the difficult IS machine environment (heat, fumes...)



RADEMA



WALL CHARGING & CALIBRATION STATION

EASY - VERSATILE - DURABLE





9 rue Jean Elysée Dupuy 69410 - Champagne au Mont d'Or- FRANCE

> Tel: + 33 (0)4 72 52 08 60 Fax: + 33 (0)4 78 47 48 66

Local Distributor